



## **STANDARD OPERATING PROCEDURE FOR PIN BOX FILLER**

**2 December 2010**

Local Sponsors shall be responsible for maintaining the pin boxes and keeping them free and clear of water and debris. The pin boxes shall be filled with a mixture of 10 W 30 motor oil and mill saw dust. The mixture should be predominantly sawdust with enough oil to protect the metal components but not to make the mixture slushy.