
VOL. 24 ISSUE 3/MARCH 2024









Commanding Officer
Capt. Tim Waits

Executive Officer
Capt. Jason S. Tarrant

Command Master Chief CMDCM (AW/SW/SS/IW) Randy F. Swanson

MEDIA DEPARTMENT

Public Affairs Officers Lt. Cmdr. Patricia A. Kreuzberger

> Ensign Hannah M. Smith


Senior Editors MCCS (SW/AW) Lori D. Bent

MCC (SW/AW) Ernest R. Scott

Editors MC1 (SW/AW) Marc O. Cuenca

<u>Layout and Design</u> MCSN Travis S. Hanes

Contributors
MC1 (SW/AW)
Marc O. Cuenca
MC2 David C. Fines
MC2 John T, Jarrett
MC2 Nicholas A. Russell
MC3 August Y. Clawson
MC3 Lucas J. Hastings
MC3 Wadelon G. Presley
MCSN Travis S. Hanes
MCSN Geoffrey L. Ottinger
























The Board of Inspection and Survey (INSURV) was initially established by Congress in 1870, with legislation enacted in 1882 to inspect our Navy ships and to report on their readiness. It is a thorough inspection that examines ships against Navy standards to determine readiness in various areas. The inspection is designed to be taken "in stride" and as an "open-book test" with the standards available beforehand.

With any inspection, ownership is a key part. Know your spaces and what your team is responsible for.

While preparing for this inspection, it not only important to go above and beyond to show the inspectors our Warfighting capabilities, but we must remember we are preparing to be the forward-deployed naval forces carrier at the tip of the spear.




















DOOR TEAM

THE DOOR TEAM ENSURES THAT EVERY SINGLE WATERTIGHT AND AIRTIGHT DOOR ONBOARD GEORGE WASHINGTON ARE IN WORKING ORDER. FROM LINKAGE TO CHALK TESTS, THEY DO IT ALL.

















LAGGING TEAM

THE LAGGING TEAM KEEPS GEORGE WASHINGTON'S SPACES INSULATED AND KEEPS PIPING ONBOARD SAFE FROM HARM AND LEAKS.









DECK TEAM


THE DECK TEAM KEEPS ALL OF OUR DECKS INSPECTION READY, FROM DEMOLITION TO REINSTALLATION.

CABLEWAY TEAM

SEE A DEAD END CABLE? CALL THE CABLEWAY TEAM. GEORGE WASHINGTON'S CABLEWAY TEAM WORKS TO MAKE SURE NO MISHAPS OCCUR.














FINISH THE JOB.

Clear zone hits before INSURV to ensure our ship will meet all conditional readiness criteria.

Contact the Maintenence Support Center (J:5546) for any ZIDL questions or concerns.

INSURV MART

MONDAY-FRIDAY 0830-1600 1-173-1-Q

EEBDS
DC EQUIPMENT
LIGHTING FIXTURES
FIXTURE LABELS
WTD PARTS
AND
MISCELLANEOUS
SUPPLIES

STOCK UP REPLACE BE PREPARED

































FOR MEDIA REQUESTS MEDIAPHOTOREQUEST@CVN73.NAVY.MIL MEDIAPRINTREQUESTS@CVN73.NAVY.MIL

DISCLAIMER: The Surveyor is an authorized publication for Sailors serving aboard USS George Washington (CVN 73). The thoughts and views expressed within belong to the authors and contributors and do not necessarily represent those of the U.S. government, the Department of Defense, the Department of the Navy, or the Commanding Officer of USS George Washington. All news releases, photos, or information for publication in The Surveyor must be submitted to the Public Affairs Officer.